



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

GENERAL SUMMARY:

Client:	N/A	
PO No.:	SX-Z260121	
Item No.:	24 items	
Product Name:	Ceramic tableware	
Quantity:	41016pcs	
Inspection location:	Chaozhou Guangdong	
Supplier:	Shunxiang ceramic	
Date of inspection:	May 20~21,2026	

OVERALL CONCLUSION:

Inspection criteria	Passed	Failed	Pending	Comments
Quantity available:	x	-	-	Remark 1
Product Conformity:	-	-	x	Remark 2
Workmanship:	x	-	-	Remark 5
Test and measurement:	-	-	x	Remark 6
Labeling:	-	-	x	Remark 3
Packing and shipping mark:	-	-	x	Remark 3,4
Result:	<input type="checkbox"/> Acceptable <input type="checkbox"/> Reject <input checked="" type="checkbox"/> Pending			

SPECIAL REMARK:

- 1.Upon the arrival, all products were finished and all packed into cartons.
- 2.There's no approved sample providing for reference during inspection.
- 3.No shipping mark and label spec. available for comparison on site.
- 4.No packing method spec. available for comparison on site.
- 5.Selected 500pcsN/A1360cartons samples for inspection, found 4pcs major defect and 15pcs minor defect, for the defects found during inspection, the inspector had already shown to the factory and requested to replace these defects.
- 6.The factory refused to draw the carton drop test.

AVAILABLE QUANTITY:

Order No.	Item No.	Order Qty		Packed		Not finished		Not packed		Inspect Qty	
		pcs	ctn	pcs	ctn	pcs	ctn	pcs	ctn	pcs	ctn
SX-Z260121	CW032FYZ00001	1824	38	1824	38	0	0	0	0	22	3
	CW001FYZ00001	1800	50	1800	50	0	0	0	0	22	3
	CW003FYZ00001	1800	75	1800	75	0	0	0	0	22	3
	CT061FYZ00001	1800	75	1800	75	0	0	0	0	22	3
	16913-1FYZ00001	1200	100	1200	100	0	0	0	0	15	3
	CW021FYZ00001	1800	50	1800	50	0	0	0	0	22	3
	18755FYZ00001	1800	75	1800	75	0	0	0	0	22	3
	CT040FYZ00001	1920	10	1920	10	0	0	0	0	25	3



Final Random Inspection Report

	15846#	1824	38	1824	38	0	0	0	0	22	3
	15678#	1824	38	1824	38	0	0	0	0	22	3
	15847#	1800	300	1800	300	0	0	0	0	22	6
	15699#	1800	50	1800	50	0	0	0	0	22	3
	15680#	1800	75	1800	75	0	0	0	0	22	3
	15841#	1800	50	1800	50	0	0	0	0	22	3
	15752#	1008	28	1008	28	0	0	0	0	13	3
	16711#-16712#	1800	50	1800	50	0	0	0	0	22	3
	16713#-16714#	1824	38	1824	38	0	0	0	0	22	3
	18983VXH	1824	38	1824	38	0	0	0	0	22	3
	18982VXH	1824	19	1824	19	0	0	0	0	22	3
	18984VXH	1800	75	1800	75	0	0	0	0	22	3
	19045VXH	1824	38	1824	38	0	0	0	0	22	3
	11591#8X0089-XY	1440	30	1440	30	0	0	0	0	17	3
	12135#8X0097-8	1440	10	1440	10	0	0	0	0	17	3
	14746#8X0097-6	1440	10	1440	10	0	0	0	0	17	3
	Total:	41016	1360	41016	1360	0	0	0	0	500	75

Lot Size	General Inspection Levels			Special Inspection Levels			
	I	II	III	S1	S2	S3	S4
2 to 8	A	A	B	A	A	A	A
9 to 15	A	B	C	A	A	A	A
16 to 25	B	C	D	A	A	B	B
26 to 50	C	D	E	A	B	B	C
51 to 90	C	E	F	B	B	C	C
91 to 150	D	F	G	B	B	C	D
151 to 280	E	G	H	B	C	D	E
281 to 500	F	H	J	B	C	D	E
501 to 1,200	G	J	K	C	C	E	F
1,201 to 3,200	H	K	L	C	D	E	G
3,201 to 10,000	J	L	M	C	D	F	G
10,001 to 35,000	K	M	N	C	D	F	H
35,001 to 150,000	L	N	P	D	E	G	J
150,001 to 500,000	M	P	Q	D	E	G	J
500,001 and over	N	Q	R	D	E	H	K



Final Random Inspection Report

Single sampling plans for normal inspection

Sample Size Code Letter	Sample Size	Acceptable Quality Levels (Normal Inspection)																					
		0.065		0.10		0.15		0.25		0.40		0.65		1.0		1.5		2.5		4.0		6.5	
		Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re
A	2																				0	1	
B	3																						
C	5																						
D	8																						
E	13												0	1									
F	20											0	1										
G	32											0	1										
H	50							0	1														
J	80					0	1																
K	125			0	1					1	2												
L	200	0	1					1	2	2	3												
M	315					1	2	2	3	3	4												
N	500			1	2	2	3	3	4	5	6												
P	800	1	2	2	3	3	4	5	6	7	8												
Q	1250	2	3	3	4	5	6	7	8	10	11												
R	2000	3	4	5	6	7	8	10	11	14	15												

Inspection standard: ANSIN/AASQC Z1.4-2003 Sampling plan: Single, Normal Inspection level: II AQL: Critical: Not Allowed.		Sample Size:500		
		Critical	Major	Minor
	AQL:	0	2.5	4.0
	Defects Found:	0	4	15
	Max. Allowed:	0	21	21

WORKMANSHIP:						
Item No.	Sample size	Defective rate	Defects Description	Cri	Maj	Min
15680#	22	4.55%	Dirty mark	0	0	1
15699#	22	4.55%	Pinhole	0	0	1
15841#	22	4.55%	Scratch mark	0	1	0
15847#	22	4.55%	Black dot	0	0	1
16711#-16712#	22	4.55%	Dirty mark	0	0	1
16713#-16714#	22	4.55%	Scratch mark	0	1	0
18755FYZ00001-XB7	22	4.55%	Color stain	0	0	1
18982VXH	22	4.55%	Black dot	0	0	1
18983VXH	22	9.1%	Pinhole	0	0	1
			Black dot	0	0	1
19045VXH	22	4.55%	Broken	0	1	0
CT040FYZ00001-XB7	25	4.0%	Black dot	0	0	1



MT-INSPECTION


Final Random Inspection Report

Report No.: MT-20260520&21-004

CT061FYZ00001-XB7	22	4.55%	Pinhole	0	0	1
CW001FYZ00001-XB7	22	4.55%	Pinhole	0	0	1
CW003FYZ00001-XB7	22	4.55%	Color stain	0	0	1
CW021FYZ00001-XB7	22	13.64%	Missing glaze	0	1	0
			Black dot	0	0	1
			Sandy mark	0	0	1
CW032FYZ00001-XB7	22	4.55%	Color stain	0	0	1
Total defect:				0	4	15
Allowed:				0	21	21
Result:				Pass		

Defect Pictures:

Item No: 15680#



N/A

Dirty mark-Minor

N/A

Item No: 15699#




N/A



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

Pinhole-Minor	N/A
Item No:15841#	
	N/A
Scratch mark-Major	N/A
Item No: 15847#	
	N/A
Black dot-Minor	N/A
Item No: 16711#-16712#	



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

	N/A
Dirty mark-Minor	N/A
Item No: 16713#-16714#	
	N/A
Scratch mark-Major	N/A
Item No: 18755FYZ00001-XB7	
	N/A
Color stain-Minor	N/A



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

Item No: 18982VXH




Black dot-Minor

N/A

N/A

Item No: 18983VXH



Pinhole-Minor



Black dot-Minor

Item No: 19045VXH



N/A



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

Broken-Major	N/A
Item No: CTO40FYZ00001-XB7	
	N/A
Black dot-Minor	N/A
Item No: CT061FYZ00001-XB7	
	N/A
Pinhole-Minor	N/A
Item No: CW001FYZ00001-XB7	



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

	<p>N/A</p>
<p>Pinhole-Minor</p>	<p>N/A</p>
<p>Item No: CW003FYZ00001-XB7</p>	
	<p>N/A</p>
<p>Color stain-Minor</p>	<p>N/A</p>
<p>Item No: CW021FYZ00001-XB7</p>	
<p>Missing glaze-Major</p>	<p>Black dot-Minor</p>



	<p>N/A</p>
<p>Sandy mark-Minor</p>	<p>N/A</p>
<p align="center">Item No: CW032FYZ00001-XB7</p>	
	<p>N/A</p>
<p>Color stain-Minor</p>	<p>N/A</p>

PRODUCT CONFORMITY & ON-SITE TESTS			
Check Points & On-site Tests	Sample Size	Criteria	Result & Remarks
<p>Visual Check (Style, Appearance, Material, Color)</p>	<p>All Sample size</p>	<p>a. Conformance to Style N/A Appearance N/A Material N/A Color compared against: <input type="checkbox"/> Client's N/A <input type="checkbox"/> Factory's ref. sample. <input checked="" type="checkbox"/> No ref. sample for comparison. (N.B.: Provide details in comment section if 2 or more color shades andN/Aor any color variation is found.)</p> <p>b. Free of nick, burrs, pits, sharp point or any other defects which may affect the product serviceability.</p> <p>c. FinishN/A coating is smooth and even without streaks, blisters, wrinkles, or runs.</p> <p>d. Good overall appearance with good alignment of components.</p>	<p>PENDING Remark 2</p>
<p>Color Fastness Test</p>	<p>S-2</p>	<p>DryN/Awet white cloth rubbing (dry white paper substitute if white cloth is not available)</p>	<p>PASS</p>



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

Silk Screen Printing Adhesive Test	S-2	Stuck the 3M tape on the printing area and stayed for 30 seconds then torn off to see printing quality.	PASS	
Color shade check	S-2	No color discrepancy	PASS	
Barcode/AQR code scanning test	S-2	Checked by scanner readable	PASS	
Export Carton Drop Test	1 Carton	Drop the carton for 10 times in the sequence of 1 corner, 3 edges and 6 faces with below criteria:	PENDING Remarks :6	
		Carton Gross Wt. (kg)		Drop Height (cm)
		0.5 kg – 9.5 kg		76cm
		≥ 9.5 kg – 18.6 g		61cm
		≥ 18.6 kg – 27.7 kg		46cm
		≥ 27.7 kg – 45.4 kg		31cm
45.4 kg – 68 kg	20cm			
Function check	S-2	All captioned function is well conducted as intended. Such as installation/Aadjusting, actual using function etc. All of function should be complied with claims.	PASS	
Stability check	S-2	Place sample on a plane at an angle of 10 degree to horizontal, and the sample can be with load as intended use and should not tip over in any of the most unfavourable positions.	PASS	
Adhesive force test	2pcs	Adhesive force testing of inner pot painting: scratch 100 grids with size 1mm*1mm them test with tape 3M	PASS	
Smell test	All Sample size	No pungent smell come out	PASS	
Capacity check	2pcs	Actual finding:	PASS	
Leak test	S-2	No leakage	PASS	

PACKING AND ACCESSORIES:

Item No.:	Master shipper (pcs/ctn)	Carton size L×W×H (cm)	G.W (Kg)	N.W (Kg)	Color box size L×W×H (cm)	Color box weight(g)	Carton Barcode	Color box Barcode
CW032FYZ00001	48	46x34.5x34	14.15	12.5	N/A	N/A	2221011230011	N/A
CW001FYZ00001	36	42.3x31x22	10.15	9.2	N/A	N/A	2221011100017	N/A
CW003FYZ00001	24	40x30.2x29.5	15	12.8	N/A	N/A	2221011300011	N/A
CT061FYZ00001	24	46x24x23.5	8.8	7.9	N/A	N/A	22210111600011	N/A
16913-1FYZ00001	12	68x34.6x34.7	11.6	9.1	N/A	N/A	2221011169137	2221011169137
CW021FYZ00001	36	34x30.5x33.8	10.55	9.1	N/A	N/A	2221011120015	2221011120015
18755FYZ00001	24	64.6x33.3x28.7	11.25	8.2	N/A	N/A	2221011187551	2221011187551
CT040FYZ00001	192	48.5x35x26.8	18.75	17.2	N/A	N/A	2221011400018	N/A
15846#	48	51.3x28.7x29.7	10.5	9	N/A	N/A	2221011518461	N/A
15678#	48	33.6x32x32.3	9.9	8.7	N/A	N/A	2221011156786	N/A
15847#	6	44.7x26.8x26.8	5.4	4.5	N/A	N/A	2221011518478	N/A
15699#	36	45.9x32.3x24	13.4	12	N/A	N/A	2221011516993	N/A
15680#	24	55.7x30.2x29	17.46	15.8	N/A	N/A	2221011516801	N/A



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

15841#	36	29x29x27.3	8.9	8	N/A	N/A	2221011518416	N/A
15752#	48	43x23.5x27.2	6.95	5.5	N/A	N/A	2221011157523	2221011157523
16711#-16712#	36	60.1x47.2x24.1	15.4	12	N/A	N/A	2221011167119	2221011167119
16713#-16714#	48	48.3x38.2x28	11	8.3	N/A	N/A	2221011167133	2221011167133
18983VXH	48	36x22.9x42.6	10.4	9.1	N/A	N/A	2221011189838	N/A
18982VXH	96	31x29.7x29.7	8.96	7.9	N/A	N/A	2221011189821	N/A
18984VXH	48	35.8x22.4x42.6	10.4	9.1	N/A	N/A	2221011189838	N/A
19045VXH	48	37x28.8x28.7	6.9	5.7	N/A	N/A	2221011190452	N/A
11591#8X0089-XY	48	38.8x26x37.7	16.7	15.2	N/A	N/A	N/A	N/A
12135#8X0097-8	144	39.8x21.3x32.7	9.5	8.4	N/A	N/A	N/A	N/A
14746#8X0097-6	144	40.5x19.8x31.7	11.1	9.9	N/A	N/A	N/A	N/A

PRODUCT SPECIFICATION:

Item No.:	Check point	Client Spec.	Ref. Sample	Sample 1#	Sample 2#	Sample 3 #
CW032FYZ00001	Size check	14x14cm	-	13.8x13.8x6.7cm	13.8x13.8x6.7cm	13.8x13.8x6.7cm
	Weight check	-	-	261g	256g	266
CW001FYZ00001	Size check	19x19cm	-	18.7x18.7x2.3cm	18.7x18.7x2.3cm	18.7x18.7x2.3cm
	Weight check	-	-	255.7g	253.1g	247.3g
CW003FYZ00001	Size check	26.7x26.7cm	-	26.4x26.4x2.4cm	26.4x26.4x2.4cm	26.4x26.4x2.4cm
	Weight check	-	-	537g	524g	538g
CT061FYZ00001	Size check	20.5x20.5cm	-	20.6x20.6x4.7cm	20.6x20.6x4.7cm	20.6x20.6x4.7cm
	Weight check	-	-	330g	328g	333g
16913-1FYZ00001	Size check	-	-	25.5x15.5x18.1cm	25.5x15.5x18.1cm	25.5x15.5x18.1cm
	Weight check	-	-	762g	783g	782g
CW021FYZ00001	Size check	-	-	9.6x9.6x8.7cm	9.6x9.6x8.7cm	9.6x9.6x8.7cm
	Weight check	-	-	254g	246g	254g
18755FYZ00001	Size check	-	-	15.1x15.1x7.8cm	15.1x15.1x7.8cm	15.1x15.1x7.8cm
	Weight check	-	-	344g	343g	353g
CT040FYZ00001	Size check	10.6x10.6cm	-	10.5x10.5x2.6cm	10.5x10.5x2.6cm	10.5x10.5x2.6cm
	Weight check	-	-	90g	86g	89g
15846#	Size check	11.5x11.5cm	-	11.4x11.4x6cm	11.4x11.4x6cm	11.4x11.4x6cm
	Weight check	-	-	189	193	193
15678#	Size check	13.6x13.6cm	-	13.6x13.6x4.7cm	13.6x13.6x4.7cm	13.6x13.6x4.7cm
	Weight check	-	-	182.4g	189.5g	181.4g
15847#	Size check	23.5x23.5cm	-	23x23x8.9cm	23x23x8.9cm	23x23x8.9cm
	Weight check	-	-	752g	755.5g	751.3g
15699#	Size check	21x21cm	-	20.8x20.8x1.9cm	20.8x20.8x1.9cm	20.8x20.8x1.9cm



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004

	Weight check	-	-	335g	348g	343g
15680#	Size check	26x26cm	-	26.5x26.5x2.7cm	26.5x26.5x2.7cm	26.5x26.5x2.7cm
	Weight check	-	-	661	663	666
15841#	Size check	25.6x6.3x2cm	-	25.6x6.1x2.3cm	25.6x6.1x2.3cm	25.6x6.1x2.3cm
	Weight check	-	-	224.2g	218.5g	219.9g
15752#	Size check	-	-	4.8x4.8x7.7cm	4.8x4.8x7.7cm	4.8x4.8x7.7cm
	Weight check	-	-	116g	118g	114g
16711#-16712#	Size check	14x14cm	-	13.8x13.8x6cm	13.8x13.8x6cm	13.8x13.8x6cm
	Weight check	-	-	336g	332g	341g
16713#-16714#	Size check	11x11cm	-	10.8x10.8x5.6cm	10.8x10.8x5.6cm	10.8x10.8x5.6cm
	Weight check	-	-	163	170	173
18983VXH	Size check	18.2x18.2cm	-	18.2x18.2x2.8cm	18.2x18.2x2.8cm	18.2x18.2x2.8cm
	Weight check	-	-	190	189	189
18982VXH	Size check	12x12cm	-	12x12x2.3cm	12x12x2.3cm	12x12x2.3cm
	Weight check	-	-	82.5g	82.5g	80.2g
18984VXH	Size check	23.5x23.5cm	-	23.2x23.2x3ccm	23.2x23.2x3ccm	23.2x23.2x3ccm
	Weight check	-	-	374.8g	376.6g	368g
19045VXH	Size check	11.5x11.5cm	-	11.4x11.4x6.3cm	11.4x11.4x6.3cm	11.4x11.4x6.3cm
	Weight check	-	-	117g	118g	120g
11591#8X0089-XY	Size check	16.9x16.3cm	-	16.6x16x1.9cm	16.6x16x1.9cm	16.6x16x1.9cm
	Weight check	-	-	317g	318g	323g
12135#8X0097-8	Size check	10.5x6.1x2.4cm	-	10.3x6x2.5cm	10.3x6x2.5cm	10.3x6x2.5cm
	Weight check	-	-	59	58	57
14746#8X0097-6	Size check	10.9x6.1x2.1cm	-	10.8x6x2.2cm	10.8x6x2.2cm	10.8x6x2.2cm
	Weight check	-	-	69g	70g	69g

EXPORT CARTON INFORMATION:

Carton:	New export carton	Yes	Sealing:	Opaque gummed tape	-
Fastening:	Metal staples	Yes		Transparent gummed tape	Yes
Strapping:	Nylonx2	No		Paper tape	-
Material:	Ply of corrugated paper	5ply	Others:	-	

Product photo show:

11591#8X0089-XY



Final Random Inspection Report



IMG_6880



IMG_6881



IMG_6882



IMG_6883



IMG_6883b (1)



IMG_6883b (2)



MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_6883b (3)



IMG_6883b (4)




IMG_6883b (5)



IMG_6883b (6)



IMG_6883b (6)b



IMG_6883b (7)b



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6884



IMG_6885



IMG_6886



IMG_6887



IMG_6888



IMG_6889



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6890



IMG_6891



IMG_6892



IMG_6893



IMG_6894



IMG_6895



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6896



IMG_6897



IMG_6898



IMG_6899



IMG_6900



IMG_6901



Final Random Inspection Report



IMG_6902



IMG_6903



IMG_6904



IMG_6905



IMG_6906



IMG_6907



MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_6908



IMG_6909



IMG_6910



IMG_6911



IMG_6912



IMG_6913

12135#8X0097-8



Final Random Inspection Report



IMG_6998



IMG_6999



IMG_7000



IMG_7001



IMG_7001b (1)




IMG_7001b (2)




Final Random Inspection Report



IMG_7001b (3)



IMG_7001b (4)




IMG_7001b (5)



IMG_7001b (6)



IMG_7001b (6)b



IMG_7001b (7)b



Final Random Inspection Report



IMG_7002



IMG_7003



IMG_7004



IMG_7005



IMG_7006



IMG_7007



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7008



IMG_7009



IMG_7010



IMG_7011



IMG_7012



IMG_7013



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7014



IMG_7015



IMG_7016



IMG_7017



IMG_7018



IMG_7019



Final Random Inspection Report



IMG_7020



IMG_7021



IMG_7022



IMG_7023



IMG_7024



IMG_7025



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7026



IMG_7027



IMG_7028



IMG_7029

14746#8X0097-6



IMG_7038



IMG_7039



Final Random Inspection Report



IMG_7040



ITEM NO.: 14746 #8X0097-6
 DESCRIPTION: 4.24" DISH
 QTY: 144 PCS
 G.W.: 12 KGS
 MEAS.: 41 X 19 X 32 CM


IMG_7041



IMG_7041b (1)



IMG_7041b (2)



IMG_7041b (3)



IMG_7041b (4)



MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_7041b (5)



IMG_7041b (6)




IMG_7041b (6)b



IMG_7041b (7)b



IMG_7042



IMG_7043



IMG_7044



IMG_7045



IMG_7046



IMG_7047



IMG_7048



IMG_7049



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7050



IMG_7051



IMG_7052



IMG_7053



IMG_7054



IMG_7055



Final Random Inspection Report



IMG_7056



IMG_7057



IMG_7058



IMG_7059



IMG_7060



IMG_7061



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7062



IMG_7063



IMG_7064



IMG_7065



IMG_7066



IMG_7067



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7068

N/A

N/A

15678



IMG_3905



IMG_3906



IMG_3907




IMG_3908



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3909



IMG_3910



IMG_3910b (1)



IMG_3910b (2)



IMG_3910b (3)



IMG_3910b (4)



Final Random Inspection Report



IMG_3910b (5)



IMG_3910b (6)



IMG_3910b (6)b



IMG_3910b (7)b



IMG_3911



IMG_3912



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3913



IMG_3914



IMG_3915



IMG_3916



IMG_3917



IMG_3918



Final Random Inspection Report



IMG_3919



IMG_3920



IMG_3921



IMG_3922



IMG_3923



IMG_3924



Final Random Inspection Report



IMG_3925



IMG_3926




IMG_3927



IMG_3928



IMG_3929



IMG_3930



Final Random Inspection Report



IMG_3931



IMG_3932



IMG_3933



IMG_3934



IMG_3935



IMG_3936



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3937



IMG_3938

15680#




IMG_7153



IMG_7154



IMG_7155



IMG_7156


Order No: SX-Z260121
 CONSIGNEE: Rimal LLC
 VENDOR: GUANGDONG SHUNXIANG PORCELAIN CO., LTD.
 PRODUCT NAME: 10.2" PLATE
 ITEM: 15680#
 PRODUCT CODE: new
 PRODUCT EAN: 2221011516801
 QUANTITY: 24 pcs/ctn
 GROSS WEIGHT: 16 kgs/ctn
 NET WEIGHT: 15 kgs/ctn
 COUNTRY OF ORIGIN: CHINA
 CARTON NUMBER: 75 of 75
 barcode:
 2 221011 516801



MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_7157



IMG_7158




IMG_7158b (1)



IMG_7158b (2)



IMG_7158b (3)



IMG_7158b (4)



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7158b (5)



IMG_7158b (6)



IMG_7158b (6)b



IMG_7158b (7)b



IMG_7159



IMG_7160



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7161



IMG_7162



IMG_7163



IMG_7164



IMG_7165



IMG_7166



Final Random Inspection Report



IMG_7167



IMG_7168



IMG_7169



IMG_7170



IMG_7171



IMG_7172



Final Random Inspection Report



IMG_7173



IMG_7174



IMG_7175



IMG_7176



IMG_7177



IMG_7178



Final Random Inspection Report



IMG_7179



IMG_7180



IMG_7181



IMG_7182



IMG_7183

N/A

N/A

15699#



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7115



IMG_7116



IMG_7117



IMG_7118



IMG_7119



IMG_7119b (1)



Final Random Inspection Report




IMG_7119b (2)



IMG_7119b (3)



IMG_7119b (4)



IMG_7119b (5)



IMG_7119b (6)



IMG_7119b (6)b



Final Random Inspection Report



IMG_7119b (7)b



IMG_7120



IMG_7121



IMG_7122



IMG_7123



IMG_7124



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7125



IMG_7126



IMG_7127



IMG_7128



IMG_7129



IMG_7130



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7131



IMG_7132



IMG_7133



IMG_7134



IMG_7135



IMG_7136



Final Random Inspection Report



IMG_7137



IMG_7138



IMG_7139



IMG_7140



IMG_7141



IMG_7142



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7143



IMG_7144

15752#




IMG_7495



IMG_7496



IMG_7497



IMG_7498




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7499



IMG_7500



IMG_7500b (1)



IMG_7500b (2)



IMG_7500b (3)



IMG_7500b (4)



Final Random Inspection Report




IMG_7500b (5)



IMG_7500b (6)



IMG_7500b (6)b



IMG_7500b (7)b



IMG_7501



IMG_7502



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7503



IMG_7504



IMG_7505



IMG_7506



IMG_7507




IMG_7508



Final Random Inspection Report



IMG_7509



IMG_7510



IMG_7511



IMG_7512



IMG_7513



IMG_7514



IMG_7515



IMG_7516



IMG_7517



IMG_7518



IMG_7519



IMG_7520



Final Random Inspection Report



IMG_7521



IMG_7522



IMG_7523



IMG_7524



IMG_7525



IMG_7526



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7527



IMG_7528



IMG_7529



IMG_7530



IMG_7531




IMG_7532



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7533



IMG_7534



IMG_7536



IMG_7537

15841



IMG_3864



IMG_3865




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3866



IMG_3867



IMG_3868



IMG_3869



IMG_3869b (1)



IMG_3869b (1)b



Final Random Inspection Report



IMG_3869b (2)



IMG_3869b (2)b



IMG_3869b (3)



IMG_3869b (4)



IMG_3869b (5)



IMG_3869b (6)



Final Random Inspection Report



IMG_3870



IMG_3871



IMG_3872



IMG_3873



IMG_3874



IMG_3875



Final Random Inspection Report



IMG_3876



IMG_3877



IMG_3878



IMG_3879



IMG_3880



IMG_3881



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3882



IMG_3883



IMG_3884



IMG_3885



IMG_3886



IMG_3887



Final Random Inspection Report




IMG_3888




IMG_3889



IMG_3890



IMG_3891



IMG_3892



IMG_3893



Final Random Inspection Report



IMG_3894



IMG_3895



IMG_3896

N/A

N/A

15846#



IMG_6960




IMG_6961



Final Random Inspection Report

MT-INSPECTION

Report No.: MT-20260520&21-004



IMG_6962



IMG_6963



IMG_6964



IMG_6964b (1)



IMG_6964b (2)



IMG_6964b (3)



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_6964b (4)




IMG_6964b (5)



IMG_6964b (6)



IMG_6964c (1)



IMG_6964c (2)



IMG_6965



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6966



IMG_6967



IMG_6968



IMG_6969



IMG_6970



IMG_6971



Final Random Inspection Report



IMG_6972



IMG_6973



IMG_6974



IMG_6975



IMG_6976



IMG_6977



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6978



IMG_6979



IMG_6980



IMG_6981



IMG_6982



IMG_6983



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_6984



IMG_6985



IMG_6986



IMG_6987



IMG_6988



IMG_6989

15847



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3947




IMG_3948



IMG_3949



IMG_3950



IMG_3951



IMG_3952



Final Random Inspection Report



IMG_3952b (1)



IMG_3952b (2)



IMG_3952b (3)



IMG_3952b (4)



IMG_3952b (5)



IMG_3952b (6)



Final Random Inspection Report



IMG_3952c (1)



IMG_3952c (2)



IMG_3953



IMG_3954



IMG_3955



IMG_3956



Final Random Inspection Report



IMG_3957



IMG_3958



IMG_3959



IMG_3960



IMG_3961



IMG_3962



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3963



IMG_3964



IMG_3965



IMG_3966



IMG_3967




IMG_3968



Final Random Inspection Report



IMG_3969



IMG_3970



IMG_3971



IMG_3972



IMG_3973



IMG_3974



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3975



IMG_3976



IMG_3977



IMG_3978



IMG_3979

N/A

N/A

16711#-16712#



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7288



IMG_7289



IMG_7290



IMG_7291



IMG_7292



IMG_7293



Final Random Inspection Report



IMG_7293b (1)



IMG_7293b (2)




IMG_7293b (3)



IMG_7293b (4)



IMG_7293b (5)




IMG_7293b (6)



Final Random Inspection Report



IMG_7293c (1)



IMG_7293c (2)



IMG_7294



IMG_7295



IMG_7296




IMG_7297



Final Random Inspection Report




IMG_7298



IMG_7299



IMG_7300



IMG_7301



IMG_7302



IMG_7303



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7304




IMG_7305




IMG_7306



IMG_7307



IMG_7308



IMG_7309



IMG_7310



IMG_7311



IMG_7312



IMG_7313



IMG_7314



IMG_7315



Final Random Inspection Report



IMG_7316



IMG_7317



IMG_7318



IMG_7319



IMG_7320



IMG_7321



Final Random Inspection Report



IMG_7322



IMG_7323



IMG_7324



IMG_7325



IMG_7326




IMG_7327



Final Random Inspection Report



IMG_7328



IMG_7329



IMG_7330



IMG_7331



IMG_7332



IMG_7333




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7334



IMG_7335



IMG_7336



IMG_7337

16713#-16714#



IMG_7231



IMG_7232




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7233



IMG_7234



IMG_7235



IMG_7236



IMG_7236b (1)



IMG_7236b (2)



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7236b (3)



IMG_7236b (4)



IMG_7236b (5)



IMG_7236b (6)



IMG_7236c (1)



IMG_7236c (2)



IMG_7237




IMG_7238




IMG_7239




IMG_7240



IMG_7241



IMG_7242




IMG_7243



IMG_7244



IMG_7245



IMG_7246



IMG_7247




IMG_7248




IMG_7249



IMG_7250



IMG_7251



IMG_7252



IMG_7253



IMG_7254



Final Random Inspection Report



IMG_7255



IMG_7256



IMG_7257



IMG_7258



IMG_7259



IMG_7260



Final Random Inspection Report



IMG_7261



IMG_7262



IMG_7263



IMG_7264



IMG_7265



IMG_7266



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7267




IMG_7268



IMG_7269



IMG_7270



IMG_7271



IMG_7272



Final Random Inspection Report



IMG_7273



IMG_7274



IMG_7275



IMG_7276



IMG_7277



IMG_7278



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7279

N/A

N/A

16913-1FYZ00001




IMG_7546



IMG_7547



IMG_7548



Order No: SX-Z260121
 CONSIGNEE: Rimal LLC
 VENDOR: GUANGDONG SHUNXIANG PORCELAIN CO., LTD.
 PRODUCT NAME: 1.3L TEA POT
 ITEM: 16913-1FYZ00001
 PRODUCT CODE: new
 PRODUCT EAN: 2221011169137
 QUANTITY: 12 pcs/ctn
 GROSS WEIGHT: 13 kgs/ctn
 NET WEIGHT: 12 kgs/ctn
 COUNTRY OF ORIGIN: CHINA
 CARTON NUMBER: 76 of 100

barcode:
 2 2221011169137


IMG_7549



Final Random Inspection Report

MT-INSPECTION

Report No.: MT-20260520&21-004



IMG_7550



IMG_7551



IMG_7551b (1)



IMG_7551b (2)



IMG_7551b (3)



IMG_7551b (4)




IMG_7551b (5)



IMG_7551b (6)



IMG_7551c (1)



IMG_7551c (2)



IMG_7552



IMG_7553



MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_7554




IMG_7555




IMG_7556



IMG_7557



IMG_7558




IMG_7559




MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_7560



IMG_7561



IMG_7562



IMG_7563



IMG_7564




IMG_7565



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7566



IMG_7567



IMG_7568



IMG_7569



IMG_7570



IMG_7571



Final Random Inspection Report



IMG_7572



IMG_7573



IMG_7574



IMG_7575



IMG_7576



IMG_7577



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7578



IMG_7579



IMG_7580



IMG_7581



IMG_7582



IMG_7583




Final Random Inspection Report




IMG_7584



IMG_7585



IMG_7586



IMG_7587



IMG_7588



IMG_7589



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7590



IMG_7591



IMG_7592



IMG_7593



IMG_7594

N/A

N/A

18755FYZ00001



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7438




IMG_7439




IMG_7440



IMG_7441



IMG_7442



IMG_7443




Final Random Inspection Report



IMG_7443b (1)



IMG_7443b (2)



IMG_7443b (3)



IMG_7443b (4)



IMG_7443b (5)



IMG_7443b (6)




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7443c (1)



IMG_7443c (2)



IMG_7444



IMG_7445




IMG_7446



IMG_7447



Final Random Inspection Report




IMG_7448




IMG_7449




IMG_7450



IMG_7451



IMG_7452



IMG_7453



Final Random Inspection Report



IMG_7454



IMG_7455



IMG_7456



IMG_7457




IMG_7458



IMG_7459




Final Random Inspection Report



IMG_7460



IMG_7461



IMG_7462



IMG_7463



IMG_7464



IMG_7465



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7466



IMG_7467



IMG_7468



IMG_7469



IMG_7470



IMG_7471



Final Random Inspection Report



IMG_7472



IMG_7473



IMG_7474



IMG_7475



IMG_7476



IMG_7477



MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_7478



IMG_7479




IMG_7480



IMG_7481



IMG_7482



IMG_7483



Final Random Inspection Report




IMG_7484




IMG_7485



IMG_7486



N/A



N/A

18982VXH



IMG_6798



IMG_6799




MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_6800



IMG_6801



IMG_6802



IMG_6803



IMG_6803b (1)



IMG_6803b (2)



Final Random Inspection Report



IMG_6803b (3)



IMG_6803b (4)




IMG_6803b (5)



IMG_6803b (6)



IMG_6803c (1)



IMG_6803c (2)



IMG_6804




IMG_6805



IMG_6806



IMG_6807



IMG_6808



IMG_6809



Final Random Inspection Report



IMG_6810



IMG_6811



IMG_6812



IMG_6813



IMG_6814



IMG_6815



Final Random Inspection Report



IMG_6816



IMG_6817



IMG_6818



IMG_6819



IMG_6820



IMG_6821



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6822



IMG_6823



IMG_6824



IMG_6825



IMG_6826



IMG_6827



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6828



IMG_6829



IMG_6830



IMG_6831

18983VXH



IMG_6922



IMG_6923



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6924



IMG_6925



IMG_6926



IMG_6926b (1)



IMG_6926b (2)



IMG_6926b (3)



IMG_6926b (4)



IMG_6926b (5)



IMG_6926b (6)



IMG_6926c (1)




IMG_6926c (2)



IMG_6927




Final Random Inspection Report



IMG_6928



IMG_6929



IMG_6930



IMG_6931



IMG_6932



IMG_6933



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6934



IMG_6935



IMG_6936



IMG_6937



IMG_6938



IMG_6939




IMG_6940



IMG_6941



IMG_6942



IMG_6943



IMG_6944



IMG_6945



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6946



IMG_6947



IMG_6948



IMG_6949



IMG_6950



IMG_6951

18984VXH



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3822



IMG_3823



IMG_3824



IMG_3825



IMG_3826



IMG_3827



Final Random Inspection Report



IMG_3827b (1)



IMG_3827b (2)



IMG_3827b (3)



IMG_3827b (4)



IMG_3827b (5)



IMG_3827b (6)



Final Random Inspection Report




IMG_3827c (1)



IMG_3827c (2)



IMG_3828



IMG_3829



IMG_3830



IMG_3831



Final Random Inspection Report



IMG_3832



IMG_3833



IMG_3834



IMG_3835



IMG_3836



IMG_3837



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3838



IMG_3839



IMG_3840



IMG_3841




IMG_3842



IMG_3843



Final Random Inspection Report



IMG_3844



IMG_3845



IMG_3846



IMG_3847



IMG_3848



IMG_3849



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_3850



IMG_3851



IMG_3852



IMG_3853



IMG_3854

N/A

N/A

19045VXH



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7077



IMG_7078



IMG_7079



IMG_7080



IMG_7081




IMG_7081b (1)



Final Random Inspection Report




IMG_7081b (2)



IMG_7081b (3)



IMG_7081b (4)



IMG_7081b (5)



IMG_7081b (6)



IMG_7081c (1)



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7087



IMG_7088



IMG_7089



IMG_7090



IMG_7091



IMG_7092



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7093



IMG_7094



IMG_7095



IMG_7096



IMG_7097



IMG_7098



Final Random Inspection Report



IMG_7099



IMG_7100



IMG_7101



IMG_7102



IMG_7103



IMG_7104



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7105



IMG_7106

CT040FYZ00001




IMG_7346




IMG_7347



IMG_7348



IMG_7349


Order No: SX-Z260121
 CONSIGNEE: Rimal LLC
 VENDOR: GUANGDONG SHUNXIANG PORCELAIN CO., LTD.
 PRODUCT NAME: 4.15"DISH
 ITEM: CT040FYZ00001
 PRODUCT CODE: new
 PRODUCT EAN: 2221011400018
 QUANTITY: 192 pcs/ctn
 GROSS WEIGHT: 18 kgs/ctn
 NET WEIGHT: 17 kgs/ctn
 COUNTRY OF ORIGIN: CHINA
 CARTON NUMBER: 2 of 10
 barcode:  2 2221011400018



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7350



IMG_7351



IMG_7351b (1)



IMG_7351b (2)



IMG_7351b (3)



IMG_7351b (4)



Final Random Inspection Report




IMG_7351b (5)



IMG_7351b (6)



IMG_7351c (1)



IMG_7351c (2)



IMG_7352



IMG_7353



Final Random Inspection Report



IMG_7354



IMG_7355



IMG_7356



IMG_7357



IMG_7358



IMG_7359



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7360



IMG_7361



IMG_7362



IMG_7363



IMG_7364



IMG_7365



Final Random Inspection Report



IMG_7366



IMG_7367



IMG_7368



IMG_7369



IMG_7370



IMG_7371



Final Random Inspection Report



IMG_7372



IMG_7373



IMG_7374



IMG_7375

CT061FYZ00001



IMG_7603



IMG_7604




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7605



IMG_7606



IMG_7607



IMG_7608




IMG_7608b (1)



IMG_7608b (2)



Final Random Inspection Report



IMG_7608b (3)



IMG_7608b (4)



IMG_7608b (5)



IMG_7608b (6)



IMG_7608c (1)



IMG_7608c (2)



Final Random Inspection Report



IMG_7609



IMG_7610



IMG_7611



IMG_7612



IMG_7613



IMG_7614



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7615



IMG_7616



IMG_7617



IMG_7618



IMG_7619



IMG_7620



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7621



IMG_7622



IMG_7623



IMG_7624



IMG_7625



IMG_7626



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7627



IMG_7628



IMG_7629



IMG_7630



IMG_7631



IMG_7632



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7633

N/A

N/A

CW001FYZ00001




IMG_6840



IMG_6841



IMG_6842



IMG_6843

Order No: SX-Z260121
 CONSIGNEE: Rimal LLC
 VENDOR: GUANGDONG SHUNXIANG PORCELAIN CO., LTD.
 PRODUCT NAME: 7.5" DESSERT PLATE
 ITEM: CW001FYZ00001
 PRODUCT CODE: new
 PRODUCT EAN: 2221011100017
 QUANTITY: 36 pcs/ctn
 GROSS WEIGHT: 12 kgs/ctn
 NET WEIGHT: 11 kgs/ctn
 COUNTRY OF ORIGIN: CHINA
 CARTON NUMBER: 28 of 50





MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6844



IMG_6845



IMG_6845b (1)



IMG_6845b (2)



IMG_6845b (3)



IMG_6845b (4)




Final Random Inspection Report




IMG_6845b (5)



IMG_6845b (6)



IMG_6845c (1)



IMG_6845c (2)



IMG_6846



IMG_6847



Final Random Inspection Report



IMG_6848



IMG_6849



IMG_6850



IMG_6851



IMG_6852



IMG_6853



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6854



IMG_6855



IMG_6856



IMG_6857



IMG_6858



IMG_6859



IMG_6860



IMG_6861



IMG_6862



IMG_6863



IMG_6864



IMG_6865



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_6866



IMG_6867



IMG_6868



IMG_6869



IMG_6870



IMG_6871

CW003FYZ00001



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7192




IMG_7193



IMG_7194



IMG_7195



IMG_7196



IMG_7197



Final Random Inspection Report




IMG_7197b (1)




IMG_7197b (2)



IMG_7197b (3)



IMG_7197b (4)



IMG_7197b (5)




IMG_7197b (6)



Final Random Inspection Report



IMG_7197c (1)



IMG_7197c (2)



IMG_7198



IMG_7199



IMG_7200



IMG_7201



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7202



IMG_7203



IMG_7204



IMG_7205



IMG_7206



IMG_7207



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7208



IMG_7209



IMG_7210



IMG_7211



IMG_7212



IMG_7213



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7214



IMG_7215



IMG_7216



IMG_7217



IMG_7218



IMG_7219



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7220



IMG_7221



IMG_7222

N/A

N/A

CW021FYZ00001



IMG_7384



IMG_7385



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7386



IMG_7387




IMG_7388



IMG_7389



IMG_7389b (1)



IMG_7389b (2)



Final Random Inspection Report




IMG_7389b (3)




IMG_7389b (4)



IMG_7389b (5)



IMG_7389b (6)



IMG_7389c (1)



IMG_7389c (2)



IMG_7390



IMG_7391




IMG_7392



IMG_7393




IMG_7394




IMG_7395



Final Random Inspection Report



IMG_7396



IMG_7397



IMG_7398



IMG_7399



IMG_7400



IMG_7401



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7402




IMG_7403



IMG_7404



IMG_7405



IMG_7406



IMG_7407



Final Random Inspection Report



IMG_7408



IMG_7409



IMG_7410



IMG_7411



IMG_7412



IMG_7413



Final Random Inspection Report



IMG_7414



IMG_7415



IMG_7416



IMG_7417



IMG_7418



IMG_7419



Final Random Inspection Report



IMG_7420




IMG_7421



IMG_7422



IMG_7423



IMG_7424



IMG_7425




MT-INSPECTION

Final Random Inspection Report


Report No.: MT-20260520&21-004



IMG_7426



IMG_7427



IMG_7428



IMG_7429

CW032FYZ00001



IMG_7642




IMG_7643




MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004




IMG_7644



IMG_7645




IMG_7646



IMG_7646b (1)



IMG_7646b (2)



IMG_7646b (3)



Final Random Inspection Report



IMG_7646b (4)



IMG_7646b (5)



IMG_7646b (6)



IMG_7646c (1)



IMG_7646c (2)



IMG_7647



Final Random Inspection Report



IMG_7648



IMG_7649



IMG_7650



IMG_7651



IMG_7652



IMG_7653



Final Random Inspection Report



IMG_7654



IMG_7655



IMG_7656



IMG_7657



IMG_7658



IMG_7659



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



IMG_7660



IMG_7661



IMG_7662



IMG_7663



IMG_7664



IMG_7665




Final Random Inspection Report




IMG_7666




IMG_7667



IMG_7668



IMG_7669



IMG_7670

N/A

N/A



Final Random Inspection Report

Test



3M tape check



3M tape check



3M tape check



3M tape check



Smell check



Smell check



Final Random Inspection Report



Water leakage test



Water leakage test



Stability test



Stability test



Stability test



Stability test



Final Random Inspection Report



Stacking test



Stacking test



Thermal shock test



Thermal shock test



Thermal shock test



Thermal shock test



Final Random Inspection Report



Volume test



Volume test



Volume test



Volume test



Volume test



Volume test



Final Random Inspection Report



Volume test




Volume test



Volume test




Volume test



Volume test



Volume test



Volume test



Volume test



Volume test



Volume test

Other photos



Factory gate



Carton storage



MT-INSPECTION

Final Random Inspection Report

Report No.: MT-20260520&21-004



Carton storage



Inspection site

--The End Of Report--