




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

## GENERAL SUMMARY:

Client:	/	
PO No.:	SX-Z260402	
Item No.:	26 items	
Product Name:	Ceramic tableware	
Quantity:	9380	
Inspection location:	Chaozhou Guangdong	
Supplier:	Shunxiang ceramic	
Date of inspection:	May 20~21,2026	

## OVERALL CONCLUSION:

Inspection criteria	Passed	Failed	Pending	Comments
Quantity available:	-	-	x	Remark 1
Product Conformity:	-	-	x	Remark 2
Workmanship:	x	-	-	Remark 5
Test and measurement:	-	-	x	Remark 6
Labeling:	-	-	x	Remark 3
Packing and shipping mark:	-	-	x	Remark 3,4
<b>Result:</b>	<input type="checkbox"/> <b>Acceptable</b> <input type="checkbox"/> <b>Reject</b> <input checked="" type="checkbox"/> <b>Pending</b>			

## SPECIAL REMARK:

- Upon the arrival, all products were finished and all packed into cartons, **the factory added the item CW032F03868-3 for inspection.**
- There's no approved sample providing for reference during inspection.
- No shipping mark and label spec. available for comparison on site.
- No packing method spec. available for comparison on site.
- Selected 200pcs/232cartons samples for inspection, found 4pcs major defect and 10pcs minor defect, for the defects found during inspection, the inspector had already shown to the factory and requested to replace these defects.
- The factory refused to draw the carton drop test.

## AVAILABLE QUANTITY:

Order No.	Item No.	Order Qty		Packed		Not finished		Not packed		Inspect Qty	
		pcs	ctn	pcs	ctn	pcs	ctn	pcs	ctn	pcs	ctn
SX-Z260402	17023#-XGPI	480	10	480	10	0	0	0	0	10	2
SX-Z260402	16510#-XGOPI	480	10	480	10	0	0	0	0	10	2
SX-Z260402	17026#-XGPI	36	1	36	1	0	0	0	0	2	2
SX-Z260402	16500#-XGPI	480	10	480	10	0	0	0	0	10	2
SX-Z260402	16659#-XO	360	10	360	10	0	0	0	0	7	2
SX-Z260402	16511#-XG	480	10	480	10	0	0	0	0	10	2
SX-Z260402	17017#-XBOPPI	160	10	160	10	0	0	0	0	3	2
SX-Z260402	17018#-XPI	960	10	960	10	0	0	0	0	19	2



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

SX-Z260402	18751F03868-3	800	10	800	10	0	0	0	0	16	2
<b>SX-Z260402</b>	<b>CW032F03868-3</b>	<b>0</b>	<b>0</b>	<b>480</b>	<b>10</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>10</b>	<b>2</b>
SX-Z260402	18518F03868-3	360	10	360	10	0	0	0	0	7	2
SX-Z260402	CW001F03868-3	480	10	480	10	0	0	0	0	10	2
SX-Z260402	CT009F03868-3	360	10	360	10	0	0	0	0	7	2
SX-Z260402	CW003F03868-3	240	10	240	10	0	0	0	0	5	2
SX-Z260402	18753F03868-3	240	10	240	10	0	0	0	0	5	2
SX-Z260402	16913-1F03868-3-CH2	120	5	120	5	0	0	0	0	2	2
SX-Z260402	CW021F03868-3-C H2	96	2	96	2	0	0	0	0	2	2
SX-Z260402	18754F-18755F03868-3-CH2	240	10	240	10	0	0	0	0	5	2
SX-Z260402	CT040F03868-3	768	4	768	4	0	0	0	0	16	2
SX-Z260402	16660F03798-XZ	480	10	480	10	0	0	0	0	10	2
SX-Z260402	CT048F03798-XZ	360	10	360	10	0	0	0	0	7	2
SX-Z260402	CT061F03798	360	10	360	10	0	0	0	0	7	2
SX-Z260402	CT009F03798-XZ	360	10	360	10	0	0	0	0	7	2
SX-Z260402	CT010F03798	160	10	160	10	0	0	0	0	3	2
SX-Z260402	CT055F03798	160	10	160	10	0	0	0	0	3	2
SX-Z260402	CT052FCL03798-Z	360	10	360	10	0	0	0	0	7	2
<b>Total:</b>		<b>9380</b>	<b>222</b>	<b>9860</b>	<b>232</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>200</b>	<b>52</b>

Lot Size	General Inspection Levels			Special Inspection Levels			
	I	II	III	S1	S2	S3	S4
2 to 8	A	A	B	A	A	A	A
9 to 15	A	B	C	A	A	A	A
16 to 25	B	C	D	A	A	B	B
26 to 50	C	D	E	A	B	B	C
51 to 90	C	E	F	B	B	C	C
91 to 150	D	F	G	B	B	C	D
151 to 280	E	G	H	B	C	D	E
281 to 500	F	H	J	B	C	D	E
501 to 1,200	G	J	K	C	C	E	F
1,201 to 3,200	H	K	L	C	D	E	G
3,201 to 10,000	J	L	M	C	D	F	G
10,001 to 35,000	K	M	N	C	D	F	H
35,001 to 150,000	L	N	P	D	E	G	J
150,001 to 500,000	M	P	Q	D	E	G	J
500,001 and over	N	Q	R	D	E	H	K

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and / or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.



# Final Random Inspection Report

## Single sampling plans for normal inspection

Sample Size Code Letter	Sample Size	Acceptable Quality Levels (Normal Inspection)																					
		0.065		0.10		0.15		0.25		0.40		0.65		1.0		1.5		2.5		4.0		6.5	
		Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re
A	2																						
B	3																						
C	5																						
D	8																						
E	13																						
F	20																						
G	32																						
H	50																						
J	80																						
K	125																						
L	200																						
M	315																						
N	500																						
P	800																						
Q	1250																						
R	2000																						

<b>Inspection standard:</b> <a href="#">ANSI/ASQC Z1.4-2003</a> Sampling plan: <i>Single, Normal</i> Inspection level: II AQL: Critical: Not Allowed.		<b>Sample Size:200pcs</b>		
		<b>Critical</b>	<b>Major</b>	<b>Minor</b>
	<b>AQL:</b>	<b>0</b>	<b>2.5</b>	<b>4.0</b>
	<b>Defects Found:</b>	<b>0</b>	<b>4</b>	<b>10</b>
	<b>Max. Allowed:</b>	<b>0</b>	<b>10</b>	<b>14</b>

<b>WORKMANSHIP:</b>						
Item No.	Sample size	Defective rate	Defects Description	Cri	Maj	Min
17023#-XGPI	10	10%	Pinhole	0	0	1
16510#-XGOPI	10	0%	No defect	0	0	0
17026#-XGPI	2	0%	No defect	0	0	0
16500#-XGPI	10	0%	No defect	0	0	0
16659#-XO	7	0%	No defect	0	0	0
16511#-XG	10	10%	Pinhole	0	0	1
17017#-XBOPPI	3	0%	No defect	0	0	0
17018#-XPI	19	15.8%	Scratch mark	0	1	1
			Sandy mark	0	0	1
18751F03868-3	16	6.25%	Pinhole	0	0	1
CW032F03868-3	10	0%	No defect	0	0	0
18518F03868-3	7	14.3%	Color stain	0	0	1
CW001F03868-3	10	0%	No defect	0	0	0



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

CT009F03868-3	7	14.3%	Pinhole	0	0	1
CW003F03868-3	5	0%	No defect	0	0	0
18753F03868-3	5	0%	No defect	0	0	0
16913-1F03868-3-CH2	2	0%	No defect	0	0	0
CW021F03868-3-CH2	2	0%	No defect	0	0	0
18754F-18755F03868-3-CH2	5	0%	No defect	0	0	0
CT040F03868-3	16	12.5%	Scratch mark	0	1	0
			Sandy mark	0	0	1
16660F03798-XZ	10	0%	No defect	0	0	0
CT048F03798-XZ	7	14.3%	Black dot	0	0	1
CT061F03798	7	14.3%	Broken	0	1	0
CT009F03798-XZ	7	0%	No defect	0	0	0
CT010F03798	3	0%	No defect	0	0	0
CT055F03798	3	0%	No defect	0	0	0
CT052FCL03798-Z	7	0%	No defect	0	0	0
<b>Total defect:</b>				<b>0</b>	<b>4</b>	<b>10</b>
<b>Allowed:</b>				<b>0</b>	<b>10</b>	<b>14</b>
<b>Result:</b>				<b>Pass</b>		

## Defect Pictures:

Item No: 17023



N/A

Pinhole-Minor


Item No: 16511



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




N/A

**Pinhole-Minor**


**Item No: 17018**



**Scratch mark-Major**



**Scratch mark-Minor**



**Sandy mark-Mionr**

N/A

**Item No: 18751F03868-3**



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



**Pinhole-Minor**

N/A

**Item No: 18518F03868-3**



**Color stain-Minor**

N/A

**Item No: CT009F03868-3**



**Missing glaze-Major**



**Color stain-Minor**



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

Item No: CT040F03868-3



Scratch mark-Major



Sandy mark-Mionr

Item No: CT048F03798-XZ



Black dot-Minor

N/A

Item No: CT061F03798



Broken-Major

N/A



# Final Random Inspection Report

## PRODUCT CONFORMITY & ON-SITE TESTS

Check Points & On-site Tests	Sample Size	Criteria	Result & Remarks												
Visual Check (Style, Appearance, Material, Color)	All Sample size	a. Conformance to Style / Appearance / Material / Color compared against: <input type="checkbox"/> Client's / <input type="checkbox"/> Factory's ref. sample. <input checked="" type="checkbox"/> No ref. sample for comparison. (N.B.: Provide details in comment section if 2 or more color shades and/or any color variation is found.) b. Free of nick, burrs, pits, sharp point or any other defects which may affect the product serviceability. c. Finish/ coating is smooth and even without streaks, blisters, wrinkles, or runs. d. Good overall appearance with good alignment of components.	PENDING Remark2												
Color Fastness Test	S-2	Dry/wet white cloth rubbing (dry white paper substitute if white cloth is not available)	PASS												
Silk Screen Printing Adhesive Test	S-2	Stuck the 3M tape on the printing area and stayed for 30 seconds then torn off to see printing quality.	PASS												
Color shade check	S-2	No color discrepancy	PASS												
Barcode/QR code scanning test	S-2	Checked by scanner readable	PASS												
Export Carton Drop Test	1 Carton	Drop the carton for 10 times in the sequence of 1 corner, 3 edges and 6 faces with below criteria: <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Carton Gross Wt. (kg)</th> <th>Drop Height (cm)</th> </tr> </thead> <tbody> <tr> <td>0.5 kg – 9.5 kg</td> <td>76cm</td> </tr> <tr> <td>≥ 9.5 kg – 18.6 g</td> <td>61cm</td> </tr> <tr> <td>≥ 18.6 kg – 27.7 kg</td> <td>46cm</td> </tr> <tr> <td>≥ 27.7 kg – 45.4 kg</td> <td>31cm</td> </tr> <tr> <td>45.4 kg – 68 kg</td> <td>20cm</td> </tr> </tbody> </table>	Carton Gross Wt. (kg)	Drop Height (cm)	0.5 kg – 9.5 kg	76cm	≥ 9.5 kg – 18.6 g	61cm	≥ 18.6 kg – 27.7 kg	46cm	≥ 27.7 kg – 45.4 kg	31cm	45.4 kg – 68 kg	20cm	PENDING Remarks :6
Carton Gross Wt. (kg)	Drop Height (cm)														
0.5 kg – 9.5 kg	76cm														
≥ 9.5 kg – 18.6 g	61cm														
≥ 18.6 kg – 27.7 kg	46cm														
≥ 27.7 kg – 45.4 kg	31cm														
45.4 kg – 68 kg	20cm														
Function check	S-2	All captioned function is well conducted as intended. Such as installation/adjusting, actual using function etc. All of function should be complied with claims.	PASS												
Stability check	S-2	Place sample on a plane at an angle of 10 degree to horizontal, and the sample can be with load as intended use and should not tip over in any of the most unfavourable positions.	PASS												
Adhesive force test	2pcs	Adhesive force testing of inner pot painting: scratch 100 grids with size 1mm*1mm them test with tape 3M	PASS												
Smell test	All Sample size	No pungent smell come out	PASS												
Capacity check	S-2	Actual finding:	PASS												
Leak test	S-2	No leakage	PASS												

## PACKING AND ACCESSORIES:

Item No.:	Master shipper ( pcs/ctn )	Carton size L×W×H (cm)	G.W (Kg)	N.W (Kg)	Color box size L×W×H (cm)	Color box weight(g)	Carton Barcode	Color box Barcode
-----------	----------------------------	------------------------	----------	----------	---------------------------	---------------------	----------------	-------------------



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

17023#-XGPI	48	38x26.5x25.5	9.5	8.6	/	/	/	/
16510#-XGOPI	48	41x32x31.5	10.95	9.79	/	/	/	/
17026#-XGPI	36	58.5x27x39	21.55	20.03	/	/	/	/
16500#-XGPI	48	39.5x24x39	14.25	13.25	/	/	/	/
16659#-XO	36	45.5x29x23.5	13.4	12.49	/	/	16976388710 859	/
16511#-XG	48	43.5x35x23	15.4	14.74	/	/	16976388710 873	/
17017#-XBOPPI	16	32.5x33.5x21	8.95	8.16	/	/	/	/
17018#-XPI	96	26x25x24.5	6.9	6.43	/	/	16976388710 903	/
18751F03868-3	80	51.5x35x30	17.4	15.52	/	/	/	/
CW032F03868-3	48	39x32.5x34	14.25	12.96	/	/	/	/
18518F03868-3	36	58.5x24x34	15.1	13.18	/	/	16976388715 854	/
CW001F03868-3	48	43x35.5x22.5	13.5	11.71	/	/	/	/
CT009F03868-3	36	49x41.5x25	15.35	13.68	/	/	/	/
CW003F03868-3	24	39x30x30	15.35	14.14	/	/	169763887117 71	/
18753F03868-3	24	51x36x21.2	16.1	15	/	/	/	/
16913-1F03868-3-CH 2	24	69x67x38	26.1	19.58	22.5x15.5x17	0.95	/	6976388711842
CW021F03868-3-CH 2	48	48x25.5x47	14.1	10.61	10.6x7x10.6	0.259	/	6976388715840
18754F-18755F0386 8-3-CH2	24	49x35x40	12.5	8.5	16x16x9	0.467	/	6976388711828
CT040F03868-3	192	48x34x26.5	17.45	17	/	/	/	/
16660F03798-XZ	48	35.5x33.5x34	11.6	12	/	/	16976388712 860	/
CT048F03798-XZ	36	68x29x46	27.45	25.3	/	/	16976388712 884	/
CT061F03798	36	45.5x36x24	13.5	12.4	/	/	/	/
CT009F03798-XZ	36	46.5x44x24.5	18.2	17.2	/	/	16976388712 952	/
CT010F03798	16	33.5x29.5x30	11.85	11	/	/	16976388712 938	/
CT055F03798	16	41.5x34x21	9.7	8.44	/	/	16976388712 945	/
CT052FCL03798-Z	36	44x26x23	11.9	11	/	/	16976388712 921	/

## PRODUCT SPECIFICATION:

Item No.:	Check point	Client Spec.	Ref. Sample	Sample 1#	Sample 2#	Sample 3 #
17023#-XGPI	Size check	11.4 * 11.4 * 6.3CM	/	11.4x11.4x6.4cm	11.4x11.4x6.4cm	11.4x11.4x6.4cm
	Weight check	/	/	180g	179g	179g
16510#-XGOPI	Size check	13.4 * 13.2 * 6.6CM	/	13.3x13,3x6.5cm	13.3x13,3x6.5cm	13.3x13,3x6.5cm
	Weight check	/	/	564g	547g	553g
17026#-XGPI	Size check	17.9 * 17.9 * 8.5CM	/	17.6x17.6x3.5cm	17.6x17.6x3.5cm	17.6x17.6x3.5cm
	Weight check	/	/	347g	343g	337g
16500#-XGPI	Size check	17.9 * 17.9 * 3.3CM	/	17.6x17.6x3.5cm	17.6x17.6x3.5cm	17.6x17.6x3.5cm
	Weight check	/	/	276g	270g	279g



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

16659#-XO	Size check	21.7 * 21.7 * 3.5CM	/	22x22x3.4cm	22x22x3.4cm	22x22x3.4cm
	Weight check	/	/	347g	343g	337g
16511#-XG	Size check	20.2 * 20 * 2.2CM	/	20.2x20.2x2.2cm	20.2x20.2x2.2cm	20.2x20.2x2.2cm
	Weight check	/	/	301g	305g	306g
17017#-XBO PPI	Size check	31 * 18.6 * 3.4CM	/	30.4x17.8xd4cm	30.4x17.8xd4cm	30.4x17.8xd4cm
	Weight check	/	/	510g	502g	547g
17018#-XPI	Size check	10.2 * 10.2 * 2.2CM	/	10.4x10.4x2.5cm	10.4x10.4x2.5cm	10.4x10.4x2.5cm
	Weight check	/	/	67g	71g	65g
18751F0386 8-3	Size check	11.6 * 11.6 * 6.1CM	/	11.5x11.5x6.2cm	11.5x11.5x6.2cm	11.5x11.5x6.2cm
	Weight check	/	/	194g	195g	194g
CW032F038 68-3	Size check	/	/	13.9x13.9x6.8cm	13.9x13.9x6.8cm	13.9x13.9x6.8cm
	Weight check	/	/	270g	259g	3266g
18518F0386 8-3	Size check	20 * 13.8 * 6.4CM	/	20.5x17x6.7cm	20.5x17x6.7cm	20.5x17x6.7cm
	Weight check	/	/	366g	367g	367g
CW001F038 68-3	Size check	19 * 19 * 2.2CM	/	19x19x2cm	19x19x2cm	19x19x2cm
	Weight check	/	/	244g	252g	248g
CT009F0386 8-3	Size check	21.6 * 21.6 * 4.1CM	/	21.6x21.6x4.5cm	21.6x21.6x4.5cm	21.6x21.6x4.5cm
	Weight check	/	/	380g	381g	390g
CW003F038 68-3	Size check	26.7 * 26.7 * 2.5CM	/	26.5x26.5x2cm	26.5x26.5x2cm	26.5x26.5x2cm
	Weight check	/	/	589g	601g	593g
18753F0386 8-3	Size check	31.8 * 18.3 * 3.8CM	/	32x19x2.5cm	32x19x2.5cm	32x19x2.5cm
	Weight check	/	/	625g	622g	629g
16913-1F038 68-3-CH2	Size check	24.9 * 15.1 * 13.5CM	/	24.5x15x17.5cm	24.5x15x17.5cm	24.5x15x17.5cm
	Weight check	/	/	816g	819g	817g
CW021F038 68-3-CH2	Size check	9 * 9 * 5.2CM	/	9.8x9.8x9cm	9.8x9.8x9cm	9.8x9.8x9cm
	Weight check	/	/	221g	241g	239g
18754F-1875 5F03868-3-C H2	Size check	12.4*9.8*6.8CM	/	12.7x9.8x6.8cm	12.7x9.8x6.8cm	12.7x9.8x6.8cm
	Weight check	/	/	354g	356g	356g
CT040F0386 8-3	Size check	10.6 * 10.6 * 2.6CM	/	10.5x10.5x2.5cm	10.5x10.5x2.5cm	10.5x10.5x2.5cm
	Weight check	/	/	80g	82g	82g
16660F0379 8-XZ	Size check	14 * 14 * 6.7CM	/	14.1x14.1x6.8cm	14.1x14.1x6.8cm	14.1x14.1x6.8cm
	Weight check	/	/	208g	217g	197g
CT048F0379 8-XZ	Size check	20.5 * 20.5 * 9.4CM	/	20.2x20.2x9.3cm	20.2x20.2x9.3cm	20.2x20.2x9.3cm
	Weight check	/	/	685g	705g	703g
CT061F0379 8	Size check	20.5 * 20.5 * 4.4CM	/	20.5x20.5x4.5cm	20.5x20.5x4.5cm	20.5x20.5x4.5cm
	Weight check	/	/	333g	328g	332g
CT009F0379	Size check	21.6 * 21.6 * 4.1CM	/	21.5x21.5x4.3cm	21.5x21.5x4.3cm	21.5x21.5x4.3cm



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003

8-XZ	Weight check	/	/	457g	443g	438g
CT010F0379 8	Size check	27.1 * 27.1 * 3.4CM	/	26.8x26.8x3.4cm	26.8x26.8x3.4cm	26.8x26.8x3.4cm
	Weight check	/	/	643g	642g	640g
CT055F0379 8	Size check	30.7 * 17.8 * 4.1CM	/	30.8x18x4.2cm	30.8x18x4.2cm	30.8x18x4.2cm
	Weight check	/	/	528g	536g	538g
CT052FCL03 798-Z	Size check	20.8 * 20.8 * 2.2CM	/	20.5x20.5x2.4cm	20.5x20.5x2.4cm	20.5x20.5x2.4cm
	Weight check	/	/	327g	329g	329g

## EXPORT CARTON INFORMATION:

<b>Carton:</b>	<b>New export carton</b>	<b>Yes</b>	<b>Sealing:</b>	<b>Opaque gummed tape</b>	-
<b>Fastening:</b>	<b>Metal staples</b>	<b>Yes</b>		<b>Transparent gummed tape</b>	<b>Yes</b>
<b>Strapping:</b>	<b>Nylonx2</b>	<b>No</b>		<b>Paper tape</b>	-
<b>Material:</b>	<b>Ply of corrugated paper</b>	<b>5ply</b>	<b>Others:</b>	-	

## Product photo show:

16500#-XGPI



IMG\_7882



IMG\_7883



IMG\_7884



IMG\_7885



# Final Random Inspection Report



IMG\_7886



IMG\_7887



IMG\_7888



IMG\_7889



IMG\_7890



IMG\_7891



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7892



IMG\_7893



IMG\_7894



IMG\_7895



IMG\_7896



IMG\_7897



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7898



IMG\_7899



IMG\_7900



IMG\_7901



IMG\_7902



IMG\_7903



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7904



IMG\_7905



IMG\_7906



IMG\_7907



IMG\_7908



IMG\_7909



IMG\_7910



IMG\_7911



IMG\_7912



IMG\_7913



IMG\_7914



IMG\_7915



# Final Random Inspection Report

IMG_7916	IMG_7917
	N/A
IMG_7918	N/A
16510#-XGOPI	
IMG_7804	IMG_7805



IMG\_7806



IMG\_7807



IMG\_7808



IMG\_7809



IMG\_7810



IMG\_7811



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7812



IMG\_7814



IMG\_7815



IMG\_7816



IMG\_7817



IMG\_7818



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7819



IMG\_7820



IMG\_7821



IMG\_7822



IMG\_7823



IMG\_7824



# Final Random Inspection Report



IMG\_7825



IMG\_7826



IMG\_7827



IMG\_7828



IMG\_7829



IMG\_7830



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7831



IMG\_7832



IMG\_7833



IMG\_7834



IMG\_7835



IMG\_7836



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7837



IMG\_7838



IMG\_7839



IMG\_7840



IMG\_7841



IMG\_7842

16511#-XG



# Final Random Inspection Report



IMG\_8473



IMG\_8474



IMG\_8475



IMG\_8476



IMG\_8477



IMG\_8478



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8479



IMG\_8480



IMG\_8481



IMG\_8482



IMG\_8483

硕加 SOLECASA			
硕加羽轻瓷釉下8英寸盘 8" PLATE			
型号号 Item No.	16511#	数量 Quantity	48 件
净重 N.W.	14 kg	毛重 G.W.	15 kg
体积 Volume	44 X 33.5 X 22.5CM	质量等级 Quality	合格品
执行标准 Executive Standard	Q/SX 3 GB 4806.4		



IMG\_8484

品牌 Brand	深圳市硕加家居文化有限公司	货号 Item No.	S9710876
地址 Address	深圳市龙岗区新黄阁涌村竹头社区壹号452号18楼F1	品名 Name	硕加羽轻瓷釉下8英寸盘 (国际 包装)
联系电话 Tel	400-850-1120	商品码 Item Code	6976388710876
网站 Website	www.solcasa.com	外箱码 Outer Box Code	1676388710876
生产商 Manufacturer	广东睿博海瓷有限公司		
地址 Address	广东省潮州市枫溪区康路工业园海博F1		



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8485



IMG\_8486



IMG\_8487



IMG\_8488



IMG\_8489




IMG\_8490



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8491



IMG\_8492




IMG\_8493



IMG\_8494



IMG\_8495



IMG\_8496



# Final Random Inspection Report



IMG\_8497



IMG\_8498



IMG\_8499



IMG\_8500




IMG\_8501



IMG\_8502



# Final Random Inspection Report



IMG\_8503



IMG\_8504



IMG\_8505



IMG\_8506



IMG\_8507



IMG\_8508



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_8509



IMG\_8510



IMG\_8511



IMG\_8512



IMG\_8513



IMG\_8514



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8515



IMG\_8516



IMG\_8517



IMG\_8518

16659#-XO



IMG\_8142



IMG\_8143




# Final Random Inspection Report



IMG\_8144




IMG\_8145



IMG\_8146



IMG\_8147



IMG\_8148



IMG\_8149



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8150




IMG\_8151



IMG\_8152



IMG\_8153



IMG\_8154



IMG\_8155



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8156



IMG\_8157



IMG\_8158



IMG\_8159



IMG\_8160



IMG\_8161



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8162



IMG\_8163



IMG\_8164



IMG\_8165



IMG\_8166



IMG\_8167



# Final Random Inspection Report



IMG\_8168



IMG\_8169



IMG\_8170



IMG\_8171



IMG\_8172



IMG\_8173



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8174



IMG\_8175



IMG\_8176



IMG\_8177



IMG\_8178



IMG\_8179



# Final Random Inspection Report



IMG\_8180



IMG\_8181



IMG\_8182



IMG\_8183



IMG\_8184



IMG\_8185



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8186

N/A

N/A

16660F03798-XZ



IMG\_8095



IMG\_8096



IMG\_8097



IMG\_8098



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_8099



IMG\_8100



IMG\_8101



IMG\_8102



IMG\_8103



IMG\_8104



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8105



IMG\_8106



IMG\_8107



IMG\_8108



IMG\_8109



IMG\_8110



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8111



IMG\_8112



IMG\_8113



IMG\_8114



IMG\_8115



IMG\_8116



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8117



IMG\_8118



IMG\_8119



IMG\_8120



IMG\_8121



IMG\_8122



# Final Random Inspection Report



IMG\_8123



IMG\_8124



IMG\_8125



IMG\_8126



IMG\_8127



IMG\_8128



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8129



IMG\_8130



IMG\_8131



IMG\_8132



IMG\_8133



IMG\_8134



# Final Random Inspection Report



IMG\_8135



IMG\_8136




IMG\_8137



IMG\_8138



IMG\_8139



IMG\_8140



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8141

N/A

N/A

16913-1F03868-3-CH2



IMG\_1200



IMG\_1201



IMG\_1202




IMG\_1203



# Final Random Inspection Report



IMG\_1204



IMG\_1205



IMG\_1273



IMG\_1274



IMG\_1275



IMG\_1276



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_1277



IMG\_1278



IMG\_1279

出品商 Brand/Operator	深圳市硕加家居文化有限公司		
地址 Address	深圳市龙岗区龙岗街道南联社区怡丰路16号远洋广场13栋405		
热线电话 Hotline	400-850-1120	网址 Web site	http://www.solecasa.cn
生产商 Manufacturer	广东顺祥陶瓷有限公司	地址 Address	广东省潮州市枫溪如意路工业园南侧B1



IMG\_1280



IMG\_1281


硕加釉中宾莉1.3L茶壶 1.3L TEA POT			
器型号 Item No.	16913-1F	数量 Quantity	24件
净重 N.W.	24 kg	毛重 G.W.	26 kg
体积 Dimension	69 X 66 X 36.5 CM	质量等级 Quality	合格品
执行标准 Executive Standard	Q/SX 3 GB 4806.4		



IMG\_1282



# Final Random Inspection Report



IMG\_1283



IMG\_1284



IMG\_1285



IMG\_1286



IMG\_1287



IMG\_1288




IMG\_1289



IMG\_1290




IMG\_1291



IMG\_1292



IMG\_1293



IMG\_1294



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1295



IMG\_1296



IMG\_1297



IMG\_1298



IMG\_1299



IMG\_1300



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1301



IMG\_1302



IMG\_1303



IMG\_1304




IMG\_1305



IMG\_1306



# Final Random Inspection Report



IMG\_1307



IMG\_1308



IMG\_1309



IMG\_1310



IMG\_1311



IMG\_1312



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_1313



IMG\_1314



IMG\_1315



IMG\_1316



IMG\_1317



IMG\_1318



# Final Random Inspection Report



IMG\_1319



IMG\_1320



IMG\_1321



IMG\_1322



IMG\_1323



IMG\_1324



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1325



IMG\_1326



IMG\_1327



IMG\_1328



IMG\_1329



IMG\_1330




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1331



IMG\_1332



IMG\_1333




IMG\_1334

17017#-XBOPPI



IMG\_7919



IMG\_7920



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_7921



IMG\_7922



IMG\_7923



IMG\_7924



IMG\_7925



IMG\_7926



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7927



IMG\_7928




IMG\_7929



IMG\_7930



IMG\_7931



IMG\_7932



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7933



IMG\_7934



IMG\_7935



IMG\_7936



IMG\_7937



IMG\_7938



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7939



IMG\_7940



IMG\_7941



IMG\_7942



IMG\_7943



IMG\_7944



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7945



IMG\_7946



IMG\_7947



IMG\_7948



IMG\_7949



IMG\_7950



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7951



IMG\_7952



IMG\_7953



IMG\_7954



IMG\_7955



IMG\_7956



IMG\_7957



IMG\_7958



IMG\_7959



IMG\_7960

17018#-XPI



IMG\_8048



IMG\_8049



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_8050



IMG\_8051



IMG\_8052



IMG\_8053



IMG\_8054



IMG\_8055



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8056



IMG\_8057



IMG\_8058



IMG\_8059



IMG\_8060



IMG\_8061



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8062




IMG\_8063



IMG\_8064



IMG\_8065



IMG\_8066



IMG\_8067



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8068



IMG\_8069




IMG\_8070



IMG\_8071



IMG\_8072



IMG\_8073



# Final Random Inspection Report



IMG\_8074



IMG\_8075



IMG\_8076



IMG\_8077



IMG\_8078



IMG\_8079



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8080



IMG\_8081



IMG\_8082



IMG\_8083



IMG\_8084



IMG\_8085



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8086



IMG\_8087



IMG\_8088



IMG\_8089



IMG\_8090



IMG\_8091




# Final Random Inspection Report



IMG\_8092



IMG\_8093




IMG\_8094


N/A

N/A

17023#-XGPI



IMG\_8187



IMG\_8188



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_8189



IMG\_8190



IMG\_8191



IMG\_8192



IMG\_8193



IMG\_8194



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8195



IMG\_8196



IMG\_8197



IMG\_8198



IMG\_8199



IMG\_8200



# Final Random Inspection Report



IMG\_8201



IMG\_8202



IMG\_8203



IMG\_8204



IMG\_8205



IMG\_8206



# Final Random Inspection Report



IMG\_8207



IMG\_8208



IMG\_8209



IMG\_8210



IMG\_8211



IMG\_8212



IMG\_8213




IMG\_8214



IMG\_8215



IMG\_8216



IMG\_8217



IMG\_8218



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8219



IMG\_8220



IMG\_8221



IMG\_8222



IMG\_8223

N/A

N/A

17026#-XGPI



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8557




IMG\_8558



IMG\_8559



IMG\_8560



IMG\_8561



IMG\_8562




IMG\_8563



IMG\_8564



IMG\_8565



IMG\_8566



IMG\_8567



IMG\_8568



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8569



IMG\_8570



IMG\_8571



IMG\_8572



IMG\_8573



IMG\_8574



# Final Random Inspection Report



IMG\_8575



IMG\_8576



IMG\_8577



IMG\_8578



IMG\_8579



IMG\_8580



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8581



IMG\_8582



IMG\_8583



IMG\_8584



IMG\_8585



IMG\_8586



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8587



IMG\_8588



IMG\_8589



IMG\_8590



IMG\_8591



IMG\_8592

18518F03868-3



IMG\_1384



IMG\_1385



IMG\_1386



IMG\_1387



IMG\_1388

硕加釉中欧碗7.8英寸沙拉碗		7.8" BOWL	
器型号 Item No.	18518F	数量 Qty	36件
净重 N.W.	14 kg	毛重 G.W.	15 kg
体积 Volume	58.5X23.5X3.5 CM		
质量等级 Quality	合格品		



IMG\_1389




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1390



IMG\_1391




IMG\_1392



IMG\_1393



IMG\_1394



IMG\_1395



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_1396



IMG\_1397



IMG\_1398



IMG\_1399



IMG\_1400



IMG\_1401



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1402



IMG\_1403



IMG\_1404



IMG\_1405



IMG\_1406



IMG\_1407



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1408



IMG\_1409



IMG\_1410



IMG\_1411



IMG\_1412



IMG\_1413



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1414



IMG\_1415



IMG\_1416



IMG\_1417



IMG\_1418



IMG\_1419



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1420



IMG\_1421



IMG\_1422



IMG\_1423



IMG\_1424



IMG\_1425



# Final Random Inspection Report



IMG\_1426



IMG\_1427



IMG\_1428



IMG\_1429



IMG\_1430



IMG\_1431



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1432



IMG\_1433



IMG\_1434



IMG\_1435



IMG\_1436



IMG\_1437

18751F03868-3



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1579



IMG\_1580



IMG\_1581



IMG\_1582



IMG\_1583



IMG\_1584



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1585



IMG\_1586




IMG\_1587



IMG\_1588



IMG\_1589



IMG\_1590



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_1591



IMG\_1592



IMG\_1593



IMG\_1594



IMG\_1595



IMG\_1596



# Final Random Inspection Report



IMG\_1597



IMG\_1598



IMG\_1599



IMG\_1600



IMG\_1601



IMG\_1602



# Final Random Inspection Report



IMG\_1603



IMG\_1604



IMG\_1605



IMG\_1606



IMG\_1607



IMG\_1608



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1609



IMG\_1610



IMG\_1611



IMG\_1612



IMG\_1613



IMG\_1614



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1615



IMG\_1616



IMG\_1617

N/A

N/A

18753F03868-3



IMG\_8224



IMG\_8225



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8226




IMG\_8227



IMG\_8228



IMG\_8229



IMG\_8230



IMG\_8231



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8232



IMG\_8233



IMG\_8234



IMG\_8235




IMG\_8236



IMG\_8237



# Final Random Inspection Report



IMG\_8238



IMG\_8239



IMG\_8240



IMG\_8241



IMG\_8242



IMG\_8243



# Final Random Inspection Report



IMG\_8244



IMG\_8245



IMG\_8246



IMG\_8247



IMG\_8248



IMG\_8249



# Final Random Inspection Report



IMG\_8250



IMG\_8251



IMG\_8252



IMG\_8253



IMG\_8254



IMG\_8255



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8256



IMG\_8257



IMG\_8258



IMG\_8259



IMG\_8260



IMG\_8261

18754F-18755F03868-3-CH2



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_1492



IMG\_1493



IMG\_1494



IMG\_1495



IMG\_1496



IMG\_1497



# Final Random Inspection Report



IMG\_1498



IMG\_1499




IMG\_1500



IMG\_1500a



IMG\_1501



IMG\_1502



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1503



IMG\_1504



IMG\_1505



IMG\_1506



IMG\_1507



IMG\_1508



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_1509



IMG\_1510



IMG\_1511



IMG\_1512



IMG\_1513



IMG\_1514



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1515



IMG\_1516



IMG\_1517



IMG\_1518



IMG\_1519



IMG\_1520



# Final Random Inspection Report



IMG\_1521



IMG\_1522



IMG\_1523



IMG\_1524



IMG\_1525



IMG\_1526




# Final Random Inspection Report




IMG\_1527




IMG\_1528



IMG\_1529



IMG\_1530



IMG\_1531



IMG\_1532



IMG\_1533



IMG\_1534



IMG\_1535



IMG\_1536



IMG\_1537




IMG\_1538



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_1539



IMG\_1540



IMG\_1541



IMG\_1542



IMG\_1543



IMG\_1544



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1545



IMG\_1546



IMG\_1547



IMG\_1548



IMG\_1549



IMG\_1550




# Final Random Inspection Report



IMG\_1551



IMG\_1552



IMG\_1553



IMG\_1554



IMG\_1555



IMG\_1556



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1557



IMG\_1558



IMG\_1559



IMG\_1560



IMG\_1561



IMG\_1562



# Final Random Inspection Report



IMG\_1563



IMG\_1564



IMG\_1565



IMG\_1566



IMG\_1567



IMG\_1568



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1569



IMG\_1570



IMG\_1571



IMG\_1571a



IMG\_1572




IMG\_1573



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1574



IMG\_1575

CT009F03798-XZ



IMG\_8262



IMG\_8263



IMG\_8264



IMG\_8265



IMG\_8266



IMG\_8267



IMG\_8268



IMG\_8269



IMG\_8270



IMG\_8271



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8272



IMG\_8273



IMG\_8274



IMG\_8275



IMG\_8276



IMG\_8277



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8278



IMG\_8279



IMG\_8280



IMG\_8281



IMG\_8282



IMG\_8283



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8284



IMG\_8285



IMG\_8286



IMG\_8287



IMG\_8288



IMG\_8289



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8290



IMG\_8291



IMG\_8292



IMG\_8293



IMG\_8294



IMG\_8295



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8296



IMG\_8297



IMG\_8298



IMG\_8299



IMG\_8300



IMG\_8301



# Final Random Inspection Report




IMG\_8302



IMG\_8303



IMG\_8304



IMG\_8305



IMG\_8306



IMG\_8307



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8308

N/A

N/A


CT009F03868-3



IMG\_8519



IMG\_8520



IMG\_8521



IMG\_8522



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8523



IMG\_8524




IMG\_8525



IMG\_8526



IMG\_8527



IMG\_8528



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8529



IMG\_8530



IMG\_8531



IMG\_8532



IMG\_8533



IMG\_8534



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8535



IMG\_8536



IMG\_8537



IMG\_8538



IMG\_8539



IMG\_8540



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8541



IMG\_8542



IMG\_8543



IMG\_8544



IMG\_8545



IMG\_8546



IMG\_8547



IMG\_8548



IMG\_8549



IMG\_8550



IMG\_8551



IMG\_8552



# Final Random Inspection Report



IMG\_8553



IMG\_8554



IMG\_8555



IMG\_8556

CT010F03798



IMG\_7754



IMG\_7755



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_7756



IMG\_7757



IMG\_7758



IMG\_7759



IMG\_7760



IMG\_7761



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_7762



IMG\_7763



IMG\_7764



IMG\_7765



IMG\_7766



IMG\_7767




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7768



IMG\_7769



IMG\_7770



IMG\_7771



IMG\_7772



IMG\_7773



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7774



IMG\_7775



IMG\_7776



IMG\_7777



IMG\_7778



IMG\_7779



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7780



IMG\_7781



IMG\_7782



IMG\_7783



IMG\_7784



IMG\_7785



# Final Random Inspection Report



IMG\_7786



IMG\_7787



IMG\_7788



IMG\_7789



IMG\_7790



IMG\_7791



IMG\_7792



IMG\_7793



IMG\_7794



IMG\_7795



IMG\_7796



IMG\_7797



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7798



IMG\_7799



IMG\_7800



IMG\_7801



IMG\_7802



IMG\_7803

CT040F03868-3




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7671




IMG\_7672



IMG\_7673



IMG\_7674



IMG\_7675



IMG\_7676



# Final Random Inspection Report



IMG\_7677



IMG\_7678



IMG\_7679



IMG\_7680



IMG\_7681



IMG\_7682



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7683



IMG\_7684



IMG\_7685



IMG\_7686



IMG\_7687



IMG\_7688



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7689



IMG\_7690



IMG\_7691



IMG\_7692



IMG\_7693



IMG\_7694



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7695



IMG\_7696



IMG\_7697



IMG\_7698



IMG\_7699



IMG\_7700



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7701

N/A

N/A

CT048F03798-XZ



IMG\_8309



IMG\_8310



IMG\_8311



IMG\_8312



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8313



IMG\_8314




IMG\_8315



IMG\_8316



IMG\_8317



IMG\_8318



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_8319



IMG\_8320



IMG\_8321



IMG\_8322



IMG\_8323



IMG\_8324



# Final Random Inspection Report

MT-INSPECTION


Report No.: MT-2026052/21-003



IMG\_8325



IMG\_8326



IMG\_8327



IMG\_8328



IMG\_8329



IMG\_8330



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003




IMG\_8331




IMG\_8332



IMG\_8333



IMG\_8334



IMG\_8335



IMG\_8336



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8337



IMG\_8338



IMG\_8339



IMG\_8340



IMG\_8341



IMG\_8342



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8343



IMG\_8344



IMG\_8345



IMG\_8346



IMG\_8347



IMG\_8348



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8349



IMG\_8350



IMG\_8351



IMG\_8352



IMG\_8353



IMG\_8354



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8355



IMG\_8356



IMG\_8357

N/A

N/A

CT052FCL03798-Z



IMG\_1439



IMG\_1440



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1441



IMG\_1442



IMG\_1443



IMG\_1444



IMG\_1445



IMG\_1446



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1447



IMG\_1448



IMG\_1449



IMG\_1450



IMG\_1451



IMG\_1452

硕加泰勒8英寸花边平盘  
8"PLATE

器型号 Item No.	CT052F	数量 Quantity	36 件
净重 N.W.	11 kg	毛重 G.W.	12 kg
体积 Volume	44 X 25.5 X 22.5CM	质量等级 Quality	合格品
执行标准 Executive Standard	Q/SX 3 GB 4806.4		

↑↑ 向上	易碎	怕湿	怕晒	怕压	检验合格	粘商品条形码
贴外箱码处						
出品商 Manufacturer	深圳市硕加家居文化有限公司					
地址 Address	深圳市龙岗区龙岗街道南联社区怡丰路16号远洋广场13栋405					
热线电话 Hotline	400-850-1120	网址 Web site	http://www.soleccasa.cn			
生产商 Manufacturer	广东顺祥陶瓷有限公司					
地址 Address	广东省潮州市枫溪如意路工业园侧B1					

↑↑ 向上	易碎	怕湿	怕晒	怕压	检验合格	QC4
货号 Item No.	S9712924					
品名 Item Name	硕加釉中泰勒8英寸花边平盘 (薄雾玫瑰)					
商品码 Barcode	6976388712924					
外箱码 Outer Box Code	16976388712921					
出品商 Manufacturer	深圳市硕加家居文化有限公司					
地址 Address	深圳市龙岗区龙岗街道南联社区怡丰路16号远洋广场13栋405					
热线电话 Hotline	400-850-1120	网址 Web site	http://www.soleccasa.cn			
生产商 Manufacturer	广东顺祥陶瓷有限公司					
地址 Address	广东省潮州市枫溪如意路工业园侧B1					

品名 Item Name	硕加釉中泰勒8英寸花边平盘 (薄雾玫瑰)		合格证
规格 Specification	205mm		等级: 合格品 (检验合格)
适用范围 Application	通用微波炉、烤箱、洗碗机		
产地 Origin	广东省潮州市		材质: 陶瓷
执行标准 Executive Standard	Q/SX 3 GB 4806.4		
生产商 Manufacturer	广东顺祥陶瓷有限公司		
地址 Address	广东省潮州市枫溪如意路工业园侧B1		
出品商 Manufacturer	深圳市硕加家居文化有限公司		
地址 Address	深圳市龙岗区龙岗街道南联社区怡丰路16号远洋广场13栋405		
全国统一热线电话 National Hot Line	400-850-1120		网址: http://www.soleccasa.cn
生产日期 Production Date	2025年03月22日		
(食品接触用)			



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1453




IMG\_1454



IMG\_1455



IMG\_1456



IMG\_1457



IMG\_1458



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1459



IMG\_1460



IMG\_1461



IMG\_1462



IMG\_1463



IMG\_1464




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1465



IMG\_1466



IMG\_1467



IMG\_1468



IMG\_1469



IMG\_1470



# Final Random Inspection Report



IMG\_1471



IMG\_1472



IMG\_1473



IMG\_1474



IMG\_1475



IMG\_1476



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1477



IMG\_1478



IMG\_1479



IMG\_1480



IMG\_1481



IMG\_1482



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1483



IMG\_1484



IMG\_1485



IMG\_1486



IMG\_1487



IMG\_1488



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1489



IMG\_1490



IMG\_1491

N/A

N/A

CT055F03798



IMG\_7998



IMG\_7999



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_8000



IMG\_8001



IMG\_8002



IMG\_8003



IMG\_8004



IMG\_8005



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_8006



IMG\_8007



IMG\_8008



IMG\_8009



IMG\_8010



IMG\_8011



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8012




IMG\_8013



IMG\_8014



IMG\_8015



IMG\_8016



IMG\_8017



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8018



IMG\_8019



IMG\_8020



IMG\_8021



IMG\_8022



IMG\_8023



# Final Random Inspection Report



IMG\_8024



IMG\_8025



IMG\_8026



IMG\_8027



IMG\_8028



IMG\_8029



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8030



IMG\_8031



IMG\_8032



IMG\_8033



IMG\_8034



IMG\_8035



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8036



IMG\_8037



IMG\_8038



IMG\_8039



IMG\_8040



IMG\_8041



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8042



IMG\_8043



IMG\_8044



IMG\_8045



IMG\_8046



IMG\_8047

CT061F03798



# Final Random Inspection Report



IMG\_8427



IMG\_8428



IMG\_8429



IMG\_8430



IMG\_8431



IMG\_8432



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8433



IMG\_8434



IMG\_8435



IMG\_8436



IMG\_8437



IMG\_8438




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8439



IMG\_8440



IMG\_8441



IMG\_8442



IMG\_8443



IMG\_8444



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8445



IMG\_8446



IMG\_8447



IMG\_8448



IMG\_8449



IMG\_8450



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8451



IMG\_8452



IMG\_8453



IMG\_8454



IMG\_8455



IMG\_8456



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8457



IMG\_8458



IMG\_8459



IMG\_8460



IMG\_8461



IMG\_8462



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8463



IMG\_8464



IMG\_8465



IMG\_8466



IMG\_8467



IMG\_8468



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8469



IMG\_8470



IMG\_8471




IMG\_8472

CW001F03868-3



IMG\_7961



IMG\_7962



# Final Random Inspection Report

MT-INSPECTION


Report No.: MT-2026052/21-003



IMG\_7963




IMG\_7964



IMG\_7965



IMG\_7966



IMG\_7967



IMG\_7968




# Final Random Inspection Report



IMG\_7969



IMG\_7970



IMG\_7971



IMG\_7972



IMG\_7973



IMG\_7974



# Final Random Inspection Report



IMG\_7975



IMG\_7976



IMG\_7977



IMG\_7978



IMG\_7979



IMG\_7980



# Final Random Inspection Report



IMG\_7981



IMG\_7982



IMG\_7983



IMG\_7984



IMG\_7985



IMG\_7986



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_7987



IMG\_7988



IMG\_7989



IMG\_7990



IMG\_7991



IMG\_7992



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7993



IMG\_7994



IMG\_7995



IMG\_7996



IMG\_7997

N/A

N/A

CW003F03868-3



# Final Random Inspection Report



IMG\_1335



IMG\_1336




IMG\_1337



IMG\_1338



IMG\_1339




IMG\_1340



# Final Random Inspection Report

MT-INSPECTION

Report No.: MT-2026052/21-003



IMG\_1340a (1)



IMG\_1340a (2)




IMG\_1341



IMG\_1342



IMG\_1343



IMG\_1344



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1345



IMG\_1348



IMG\_1349



IMG\_1350



IMG\_1351



IMG\_1352



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1353



IMG\_1354



IMG\_1355



IMG\_1356



IMG\_1357



IMG\_1358



IMG\_1359



IMG\_1360



IMG\_1361



IMG\_1362



IMG\_1363



IMG\_1364



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1365



IMG\_1366



IMG\_1367



IMG\_1368



IMG\_1369



IMG\_1370



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1371



IMG\_1372



IMG\_1373



IMG\_1374



IMG\_1375



IMG\_1376



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_1377



IMG\_1378



IMG\_1379




IMG\_1380




IMG\_1381



IMG\_1382



IMG\_1383



N/A

N/A

CW021F03868-3-CH2



IMG\_8358



IMG\_8359



IMG\_8360



IMG\_8361




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8362



IMG\_8363



IMG\_8364



IMG\_8365



IMG\_8366



IMG\_8367



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003




IMG\_8368



IMG\_8369




IMG\_8370



IMG\_8371



IMG\_8372



IMG\_8373



# Final Random Inspection Report




IMG\_8374



IMG\_8375



IMG\_8376



IMG\_8377



IMG\_8378



IMG\_8379



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003




IMG\_8380



IMG\_8381



IMG\_8382



IMG\_8383



IMG\_8384



IMG\_8385



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-202605/21-003



IMG\_8386



IMG\_8387



IMG\_8388



IMG\_8389



IMG\_8390



IMG\_8391



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8392




IMG\_8393



IMG\_8394



IMG\_8395



IMG\_8396




IMG\_8397



# Final Random Inspection Report



IMG\_8398



IMG\_8399



IMG\_8400



IMG\_8401



IMG\_8402



IMG\_8403



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8404



IMG\_8405



IMG\_8406



IMG\_8407



IMG\_8408



IMG\_8409



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_8410



IMG\_8411



IMG\_8412



IMG\_8413



IMG\_8414



IMG\_8415



# Final Random Inspection Report



IMG\_8416



IMG\_8417



IMG\_8418



IMG\_8419



IMG\_8420








IMG\_8421



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003

	
<p>IMG_8422</p>	<p>IMG_8423</p>
	
<p>IMG_8424</p>	<p>IMG_8425</p>
	<p>N/A</p>
<p>IMG_8426</p>	<p>N/A</p>
<p>CW032F03868-3</p>	




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7843



IMG\_7844



IMG\_7845



IMG\_7846



IMG\_7847



IMG\_7848




MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7849




IMG\_7850



IMG\_7851



IMG\_7852



IMG\_7853



IMG\_7854



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7855



IMG\_7856



IMG\_7857



IMG\_7858



IMG\_7859



IMG\_7860



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7861



IMG\_7862



IMG\_7863



IMG\_7864



IMG\_7865



IMG\_7866



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



IMG\_7867



IMG\_7868



IMG\_7869



IMG\_7870



IMG\_7871



IMG\_7872



# Final Random Inspection Report



IMG\_7873



IMG\_7874



IMG\_7875



IMG\_7876



IMG\_7877



IMG\_7878



MT-INSPECTION

# Final Random Inspection Report


Report No.: MT-2026052/21-003



IMG\_7879



IMG\_7880



IMG\_7881

N/A

N/A

Test



3M tape test



3M tape test



# Final Random Inspection Report



3M tape test



3M tape test



3M tape test



3M tape test



Smell check



Smell check



# Final Random Inspection Report



Stability test



Stability test



Stability test



Stability test



Stability test



Hot water test



# Final Random Inspection Report



Hot water test



Hot water test



Hot water test



Hot water test



Hot water test



Hot water test



# Final Random Inspection Report



Water leakage test



Water leakage test



Water leakage test



Capacity test



Capacity test



Capacity test



# Final Random Inspection Report



Capacity test




Capacity test



Capacity test



Capacity test



Capacity test



Capacity test



# Final Random Inspection Report



Capacity test



Capacity test



Capacity test



Capacity test



Capacity test



Capacity test



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



Capacity test



Capacity test



Capacity test

N/A

N/A

## Other photos



Factory gate



Carton storage



MT-INSPECTION

# Final Random Inspection Report

Report No.: MT-2026052/21-003



Carton storage



Inspection site

**--The End Of Report--**